

Bishop, Everett

From: Duffy, Rick
Sent: Thursday, April 07, 2016 11:27 AM
To: Bishop, Everett
Subject: RE: (b) (6) - Eastern Shore

Will a report containing these results be provided to the management company and to the resident?

From: Bishop, Everett
Sent: Thursday, April 07, 2016 11:25 AM
To: Duffy, Rick <Duffy.Rick@epa.gov>
Subject: FW: (b) (6) - Eastern Shore

Rick –

Rich Ponak's summary of his visit to (b) (6).

Everett Bishop
US EPA
Office of Compliance
(202) 564-7032
bishop.everett@epa.gov

From: Ponak, Rich
Sent: Thursday, April 07, 2016 10:06 AM
To: Bishop, Everett <Bishop.Everett@epa.gov>
Cc: El-Abdaoui, Fatima <El-Abdaoui.Fatima@epa.gov>
Subject: RE: (b) (6) - Eastern Shore

Everett,

During my inspection on March 30, 2016 I collected five samples. All samples were none detect. I have also requested the abatement project documents from the owner. The abatement contractor removed two sliding glass doors and a small amount of dry wall associated with each door. This work was done under containment. The front door and a window were replaced without the dry wall being disturbed. I believe this is a non-enforcement asbestos issue and is a civil issue between the owners and tenants.

Thanks, Rich

From: Bishop, Everett
Sent: Tuesday, April 05, 2016 3:46 PM
To: Ponak, Rich <Ponak.Rich@epa.gov>
Subject: (b) (6) - Eastern Shore

Rich –

Just following up on your site visit to the Wight Bay Condos. Were samples taken? What can you report?

Thanks.

Everett Bishop
US EPA
Office of Compliance
(202) 564-7032
bishop.everett@epa.gov